



Toyota Avensis Verso

Wrong refrigerant charge instruction

On some of the above-mentioned vehicles, the charge amount information (100-150 gram) on the sticker in the engine compartment is incorrect.

The correct amount of refrigerant is:

470 – 530 gram (without rear a/c)

770 – 830 gram (with rear a/c)



Bulletin