Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall July 22, 2011 1-1

VOLVO C30, S40, V50 Year of manufacture: May 2006 - January 2007 Engine: all 4 cylinder petrol engines

Radiator fan module / Coolant temperature

Problem:

Water gets into the radiator fan module. This can lead to a short circuit and breakdown of the module. In the extreme case, there is danger of fire.

Steps taken:

The vehicle manufacturer has already taken up the problem and has notified the owners of the affected vehicles. Nevertheless, one may assume that for various reasons not all vehicles have been checked and repaired.

Remedy:

As part of the review, determine which radiator fan module is installed. A service kit will be installed on affected modules. This contains a protective cap for the control model and an additional cable tree.

Important notice:

Please take this information into account when there are complaints about the ventilator fan or the coolant temperature.

Bulletin

