



Volvo

S60, S80, V70, XC70

Model year: 1999–2001

Failure of the radiator fan / Radiator fan and/or engine overheated

In the case of the above-mentioned vehicles, an electrical defect of the radiator fan/radiator fan control unit can lead to the failure/overheating of the radiator fan. In extreme cases, the overheated radiator fan can set off a fire in the engine bay. Due to the failure of the radiator fan, the engine may overheat.

The vehicle manufacturer informed all vehicle owners affected and asked them to have their vehicles checked at an authorized garage. It has to be assumed that vehicles that have not been checked or modified for various reasons are still in circulation.

If you find a vehicle with the above-mentioned problem, please contact the vehicle manufacturer or an authorized dealer.

Bulletin