



VOLVO

S 80

Year of manufacture: 2006 - 2007

With diesel engine

Defective auxiliary heater Discharged battery

Problem:

Defective auxiliary heater, discharged battery

Possible cause:

A short circuit of the electric interior auxiliary heater can lead to battery discharge. In extreme cases a fire in the area of the dashboard may be caused.

Solution of the problem:

The problem has already been dealt with by the manufacturer and a recall campaign started. However, there is a possibility that for various reasons not all vehicles have been checked and/or repaired.

During the recall campaign the electric auxiliary heater was replaced. It is not known how the performed measure was documented.

Please observe this information in the course of complaints, particularly such regarding a discharged battery.

Bulletin