



Volvo

XC 90

Model year: 2006 + 2007

Engine: 3.2 i (B6324S)

Faulty functions of the air-conditioning system

With the above-mentioned vehicles, there can be problems with the air-conditioning functions (e.g. window defrost function deactivated). The reason for this could be a faulty signal interpretation in the CAN databus system, which is caused after the key is inserted into the ignition lock. In this case, a software update should provide the remedy. Contact an authorised Volvo dealer for this purpose.

Bulletin