



VW

Failure of the pressure sensor

A permanent on/off- switching of the air-conditioning system can be caused by a faulty pressure sensor (not pressure switch). For example, water admission among others can lead to a malfunction of the sensor. This concerns particularly sensors before the production date: January 2000 .

The production date on the pressure sensor is indicated by a six-digit code number (see picture: 020201=02.02.2001).



Bulletin