## **Bulletin**



| © Hella KGaA Hueck & Co., | 29.08.2008 | 1-1 |
|---------------------------|------------|-----|
| Lippstadt/Germany         |            |     |

**VW** Fox (5Z1)

**Model year: 2005 to 2007** 

**Engine: 1.4 TDI (BNM)** 

## Failure of the fuel pre-supply pump

With the above-mentioned vehicles, the electrical pre-supply pump (see image) for fuel supply can fail. The vehicle can then no longer be started up. Vehicle owners are being informed by the vehicle manufacturers and instructed to have the pump replaced free of charge. It is possible that not all vehicle owners will follow this instruction or that not all vehicles are followed up. Please take this information into account when considering the cause of broken-down vehicles or customer complaints.



