

© Behr Hella Service GmbH, Schwäbisch Hall

Q4 / 2012

Volkswagen Golf IV With manual temperature control

Air recirculation function

The above vehicles can experience a supposed failure of the air recirculation function.

The indicator light in the air recirculation switch (figure) can fail prematurely in the above vehicles. This mistakenly leads to the assumption that there is an electrical fault in the switch. Before replacing the switch or carrying out extensive troubleshooting, the light bulb should be checked or replaced to make sure it works.



Bulletin





1-1