

© Hella KGaA Hueck & Co., Lippstadt

19. Februar 2002

\_\_\_\_

## VW Golf/Bora/Passat '98. Noises from the Instrument panel

Creak noises in the area from the fuse box cover and the dashboard.

## Cause:

Some of the above listed vehicles, experience this noise in the area of the main fuse panel in the dashboard. This noise is caused by the rubbing of the fuse box against the fuse box cover (Fig 1).



Remove the fuse box lid and the cover. Loosen the screw (Fig 2), push the fuse box to the inside and re-tighten the screw. The distance between the fuse box and cover is increased, so that no more noises arise (Fig 3). Replace the cover and fuse box cover.



Fig 3





Fig 1

## Bulletin



