

© Hella KGaA Hueck & Co., Lippstadt

24. Mai 2005

VW Lupo

Engine cannot be started up.

If there are complaints with these vehicles that the engine cannot be started up, one possible cause is a faulty ignition starter switch. Contact problems between terminal 15 and 50 or poor guidance of the connection plug prevent the engine from being started.

To eliminate the fault the ignition starter switch must be replaced by a more recent version.

Improved ignition starter switches were used in production from February 2001 onwards.

Bulletin





1-1