



## ***VW New Beetle Model year 2001***

### **Failure of the electrical window winder after repeated activation.**

If there are complaints with these vehicles that the window winders do not work after they have been activated several times, one possible cause is overheating protection. Since the window winder motor becomes very hot when it has been activated several times, there is a switch-off function installed in the software to prevent damage due to overheating. After a cooling period of approx. 3-5 minutes the window winder motor works perfectly again.

**Bulletin**