Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 29 June 2007 1-1

VW Passat (3C) Model year: 2005 to 2007 Engine: All TDI engines

Fuel cooler / Fuel loss

In the case of the above-mentioned vehicles, the mounting bracket (see photo) of the fuel cooler can break. This can lead to an uncontrolled knocking around of the cooler. As a consequence of this, fuel can escape due to leaks. The vehicle manufacturer has informed all vehicle keepers and asked for the vehicles to be checked at an authorized garage. It must be assumed that there are nevertheless vehicles in circulation which, for various reasons, have not been checked or modified.

Please take this into account in the event of complaints with regard to noises/leaks, and also take this into account within the framework of a service.



Bulletin

