

© Hella KGaA Hueck & Co., Lippstadt

29. November 2005

VW Passat 3B, Golf IV, New Beetle With leather interior

Insufficient heating power of the seat heating.

If there are complaints with these vehicles that the seat heating is insufficient in seat positions 1 to 4 and too hot in position 5, one possible cause is the seat heating switch. This switch was adapted to the leather trim in 2001. The temperature set does not correspond to the passenger's wish, however. To achieve better temperature regulation, the seat heating switches for fabric seats can be installed.

Bulletin





1-1