Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 01. Oktober 2005

VW Polo Type: 6N2 Chassis No..: 6NYY500001 - 6NYY600000

Noises from the centre vent

It is possible on this vehicle, an opened centre vent flap makes rattling noises at higher blower speeds.

This is due to a too big a gap between the fixing and the thumb wheel.

To remedy this, lubricate the adjusting rod using a lubricant suitable for use with sythetic material.



Bulletin

