



## *VW Transporter T4 from 9/95 TDI Diesel Engine Motor Code: ACV*

On vehicles with a 75KW TDI diesel engine, the poly-V-belt was sometimes not correctly fitted (see picture). This makes itself noticeable by squealing when starting, accelerating and stopping the engine. If the above happens then the belt-run should be checked and if necessary changed. The belt may also require renewing. It must run from the alternator over the tensioner pulley to the compressor.

