



VW

Transporter (T4)

Model year : 1992 - 2000

Engine: ABL (1.9 TD)

Oil-pressure control lamp lights up / flashes

If the oil-pressure control lamp lights up or flashes in the above vehicles, a faulty electrical connection at the generator could be the cause.

Understandably, when there is a lack of oil pressure, the mechanic checks the oil pressure first and replaces the oil-pressure switch if necessary. This does not always eliminate the problem. With the above-mentioned vehicle, the electrical connections at the generator should also be checked.

Corroded or loose connections (terminal "W" = speed signal) can lead to the oil-pressure control lamp lighting up/flashing due to "return current/fault current" in the instrument cluster. This information might also be applicable for other vehicles, models and engine versions.

Bulletin

