Bulletin



© Hella KGaA Hueck & Co., Lippstadt

10. September 2001

1_1

Additional fitted headlamp baffles

Leaky headlamps by Opel Astra G/ Golf IV which have additional mounted headlamp baffles.

With the use of ever decreasing gaps between bodywork and components, it is possible, through mounting optical baffles, that the headlamps become damaged and leak.

Due to the mounting of the baffles the gap between the

headlamp and the bonnet closes. Therefore the bonnet presses on the headlamp, which causes the headlamp to develop leaks and additionally paint damage to the bonnet can occur.

For this reason it is absolutely necessary to ensure that a sufficient gap exists after mounting to prevent any damage.

Bulletin

