

SERVICE-INFO



Difficult gear selection and/or clutch pedal pulsates

Seat Alhambra 1.9 TDi
Ford Galaxy 1.9 TDi
VW Sharan 1.9 TDi

We have had a number of enquiries on the above vehicles when the customer is complaining of either; poor gear selection, clutch pedal vibration or in extreme cases the pedal being drawn to the floor when driving.

This can often be misdiagnosed as a failed Dual Mass Flywheel. Before replacing the DMF the input shaft should be checked for excessive movement as this can sometimes be the primary cause of the complaint.



If excessive movement is found then the gearbox must either be overhauled or replaced.