



Air mass sensors: Note assignment!

Vehicle	Product	PIERBURG No.
BMW, Fiat; Opel; Volvo	Air mass sensor	7.22701.04/.05.0/.08.011.0; 7.22684.07.011.0



Potential complaints:

- Loss of power
- Black smoke
- Jerking
- Limp home function
- Fault lamp comes on
- Fault code P0100

One cause for the complaints listed could be that, when replaced, an air mass sensor has been installed that is not suitable for the vehicle.

Air mass sensor plug-in probes look extremely similar to one another. However, the integrated electronic modules contain different characteristic curves adapted for the specific engine type.

If an air mass sensor is used in the incorrect vehicle, in addition to the complaints mentioned it can also result in severe consequential damage.



Air mass sensor (plug-in probe)

! When ordering, make sure that you specify the exact engine type and any possible delineation by chassis number, engine code and year of manufacture.

Please use the current data records for an order:

- Motor Service Online Shop (updated every day): www.onlineshop.ms-motor-service.com
- Motor Service Product Disc From Version 5.2
- TecDoc CD and systems based on TecDoc data from Version 2/2010
- PIERBURG catalogue, from 2010 version

The right of changes and deviating pictures is reserved. Assignment and usage, refer to the each case current catalogues, TecDoc CD respectively systems based on TecDoc.