2017

Technical.bulletin

Insufficient clearance between the brake pad and the calliper

Part Number: 301825

For Vehicle: Opel Corsa 2006>

The Valeo Service Technical department have received several claims stating that after fitment of brake pads 301825 there is a squeaking noise from the front brakes when braking.

After further investigation, Valeo technicians have identified that the brake pads are not at fault. The actual cause is as a result of insufficient clearance between the brake pad and the calliper piston.

To avoid this issue, whilst installing the brake pads, make sure the brake piston cap is installed as shown.





