

826033 / 826565 engine vibration

Part Number: 826033 / 826565

For Vehicle: Citroen Berlingo

On this vehicle the engine cover mounts are prone to damage. If these mounts are damaged or worn vibration can be felt through the transmission during start up, moreover this causes the oil filler cap to loosen which produces an oil leak from the engine.

There are multiple engine mounts on the vehicle but in particular one at the back of the engine near the bottom bracket which attaches the engine to the body is particularly prone to wear. Over time, and if not attended to, it will cause the engine to rock back and forth.



Check the oil filler cap is not loose and pay special attention the engine mounts