Technical.bulletin

251496 horn function failures

Part Number: 251496

For Vehicle: Citroen Berlingo, Peugeot Partner

Please note there is a recognised fault on Citroen Berlingo and Peugeot Partner models where the wiring loom leading to the brake light switch is damaged. This damage leads to premature failure of the horn.

Before replacing Valeo column switch 251496 it is good practice to check the brake light switch is in good working order. Visible signs of damage to the vehicle wiring loom leading to the brake light switch, the engine compartment fuse box and the body control unit can lead to failure of the horn function and/or the low beam light function.



Example of brake light switch and wiring



Valeo 251496



^{*}Always follow vehicle manufacturer specification.

^{*}Claims related to horn and lighting function failure due to vehicle fault will void the warranty.