

Vehicle non start due to faulty relay

Part Number: 455720, 432644, 726008

For Vehicle: Daewoo Korando 2.3/2.9 1999>

The Valeo Service Technical department have received several claims stating that after fitment of starter motors 455720, 432644 and 726008, the starter motor does not turn the engine over.

After investigating the issue, Valeo technicians have identified that the starter motor itself is not at fault. The fault is caused by a faulty starter motor relay (R5).

Before returning or supplying a new starter motor, please check the relay in the circuit as detailed below and replace if necessary.

