



# Ford Transit 2.4Di


Fitted with replacement solid flywheel clutch system

CLTB 0014

## IMPORTANT!

Please ensure that the vehicle is suitable for a HKF1001 4-in-1 DMF replacement by following the application limitations governed below

HKF1001 is **NOT** suitable for TDCi vehicles




HKF1001 is **NOT** suitable for the 'New Transit'




Only replace if the existing replacement solid flywheel is **identical to type A**

**DO NOT FIT** to vehicles with a type B flywheel

type A



type B



Timing mark differences between the early and later type flywheels will cause non-start of the engine if HKF1001 is fitted to a 'New Transit' model year 2006>



[www.borgandbeck.com](http://www.borgandbeck.com)

TECHNICAL INFORMATION