

# Technical Bulletin



## WARNING:



Please check the rubber seal on your brake vacuum pump (see photo) which creates a seal within the camshaft oil feed journal.

If your seal does not create a seal, please replace it with the new "O" ring supplied.

Be sure to lubricate the seal before you install it into the camshaft.



Certificate No. GB00454

LEAF 9063

