

## Cooling



# PSA Thermostat Replacement

**Applicable vehicles:** Citroën C3, C4, DS3, Peugeot 207, 208, 308, 3008, 5008, RCZ, Partner, BMW MINI

Date Issued: 12/2016

COTB 0020

## Applicable References:


FTK100, FTK102, FTK396, FTK422

Before supplying and fitting part numbers FTK100, FTK102, FTK396, FTK422, it is important to ensure that the correct diagnosis has been carried out.

It is not uncommon for the applicable vehicles to display symptoms such as an erratic temperature gauge; erratic running; radiator fan run-on, or poor heater function, however it must not be assumed that the Thermostat is the cause.



On the applicable vehicles, there is a known problem relating to the Engine ECU Software being corrupt or outdated. Therefore, it is advised that before any components are replaced, the software is checked and re-programmed / flashed as needed to make sure that it is operating with the latest version.



### CAUTION:

Failure to carry out a software check will result in unnecessary time being wasted fitting components that will not cure the problem. It will also mean that these products, if returned under warranty, will likely be rejected unless a manufacturer defect is identified as the cause of failure.