

© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

## Audi A4 | A6 Type 8E | 8H | 4B

## Radiator fan without function, increased engine temperature.

If there are complaints with these vehicles that the radiator fan is not working and the engine becomes too hot, one possible cause is a faulty control unit for the radiator fan. To eliminate the fault the control unit has to be checked. This fault effects control units produced **up to** August 2002. The date of manufacture can be found on the label on the control unit. Faulty control units must be replaced by a modified version with a more recent date of manufacture.



Date of manufacture (Year 01 / Day 92)





1-1