



Audi A6 (4B..) All models

“Door open” displayed in the instrument cluster, interior lighting not working, anti-theft alarm triggered erroneously.

If there are complaints with these vehicles that an open door is indicated in the instrument cluster when the doors are closed, that the interior lighting is not working, or that the anti-theft alarm is triggered erroneously, one possible cause is a defective microswitch in the door lock. To carry out troubleshooting, suitable diagnosis equipment can be used to take a readout of the fault memory, and the operation of the microswitches can be checked in the measured-value blocks. In order to eliminate the fault, the door lock with the defective microswitch must be replaced.