

© Hella KGaA Hueck & Co., Lippstadt

8. August 2003

. .

Audi A6 build year up to 1997 A4 build year up to 2001

Non-functioning automatic opening and closing of the power windows after disconnecting the battery.

After disconnecting the battery, the automatic opening and closing is functionless. The automatic must be reinitialised after connecting the battery. For this consider the following steps:

- Switch the ignition key to position one.
- Fully close the power window using the switch (picture) to the top stop.
- Release the switch and lift it up again for one second.

Repeat this procedure for the other power windows.



Power window switch (Audi A4)



