Bulletin



© Hella KGaA Hueck & Co., Lippstadt 25. Oktober 2005 1-1

Audi All models from 2002 with alarm system

The alarm is triggered after the vehicle has been opened manually.

If there are complaints with these vehicles that the alarm is triggered after the driver door has been unlocked, this is not a fault but rather an additional safety feature. It works as follows: If the vehicle is unlocked at the driver door, only the driver door opens. All the other doors remain locked. If the ignition is not switched on within 15 seconds the alarm is triggered.

If the ignition is switched on within 15 seconds, all the other doors are unlocked and the alarm system deactivated. This additional function is installed in all Audi vehicles from model year 2002.



