



## **Audi TT Coupe and Roadster**

### **Red LED in the door panelling stays lit after the interior monitoring has been deactivated.**

If there are complaints with these vehicles that the red LED in the door panelling stays lit after the interior monitoring has been deactivated, this could be caused by a problem with the software. In this case the software in the control unit for the central locking system is faulty.

To eliminate the fault a new central locking control unit with modified software has to be installed.

From April 2001 a control unit with modified software was installed in the factory in vehicles from chassis numbers:  
8N 11 036639 (TT Roadster) and 8N 11 041775 (TT Coupe).



LED in the door panelling