



BMW 1-series (E81) Model year: 2007 - 2011 All with start-stop system

Failure of automatic start-stop No error code

If failure of the automatic start-stop is detected on the above vehicle model, this may be associated with a problem of the starter battery. One of the basic preconditions for automatic shutdown of the engine during vehicle operation is that the charge state of the battery is sufficient.

The energy management system monitors the battery conditions and charging cycles of the past 5 days.

If the minimum battery charge state required by the system (approx. 60%) is not reached, the system is switched off. In this case, the battery should first be checked, recharged or replaced.

One of the most frequent causes of an insufficient charge state is an unfavourable driving profile, also called short-distance driving.