



BMW

3-series Coupe (E92)

Model year: from 2006

Engine: N52B25 | N52B25A | N52B25C

Poor cooling performance of the air-conditioning system

With the above-mentioned vehicles, contraction of the air-conditioning hose can lead to diminished performance of the air-conditioning system.

If the high and low-pressure values deviate from standard, have a close look at the low-pressure hose that leads to the compressor before you replace the compressor and/or the expansion valve. In some cases, the hose can contract during operation of the air-conditioning system on account of the suction effect. Visual and pressure tests do not reveal anything unusual.

The hose has to be replaced for the situation to be remedied.

Please bear this information in mind whenever there are complaints about poor air-conditioning system performance or unusual pressure conditions.

This information may also be applicable for other vehicle types.

Bulletin