



BMW 5 series (E34) M50 / M51

Grumbling noises of the A/C

If roaring- or grumbling noises are experienced, the cause could be the expansion valve. These noises occur mainly at idle. Under certain conditions vibration resonance of 60 Hz can be achieved.

Between 20.05.92 and 08.07.92, the expansion valve was installed and can be recognized by the pale green colour. To remedy the valve must be changed.

Spare part: 8 UW 351 239-301



Bulletin