



BMW E39 up to model year: 03/1996

Stop light stays switched on

With the above-mentioned vehicles the stop light could stay on for up to 3 minutes after the ignition has been switched off. This is usually caused by the lamp control module (LCM) not recognising the switching-off of terminal "R" (ignition key position 1) and continuing to trigger the stop light. In this case the LCM must be re-coded.