



BMW E39, E46, E53 up to model year: 06/2001

Heater fan fails or runs permanently

In the case of the above-mentioned vehicles with manual or automatic air conditioning, the heater fan can sometimes fail sporadically, or, despite the fan setting being changed manually, continues to run at an unchanged speed. In the automatic air conditioning control panel (photo), the fan setting is displayed without change. This is usually caused by a faulty heater fan power control unit, and not by a fault in the air conditioning control panel.



Bulletin