


© Behr Hella Service GmbH, Schwäbisch Hall



## **BMW E46** with climate control

## LED in the climate button flashes after renewal the control panel

On these vehicles (with climate control) it is possible that the LED in the a/c button flashes after renewal of the control panel. This indicates, that the air-conditioning system is locked in the compressor protection mode. As the spare part is identical with the series part, the LED (see picture) flashes so long, unil the compressor has run for approx. 90 seconds at an engine speed of under 1500 rpm.

This ensures that the refrigerant is spread througout the system before the engine is revved higher. This happens with new vehicles, through the renewal of the control panel this function is repeated as if it were a new vehicle.



Bulletin





1-1