



BMW E46

Engine: M43

Model year: from 06/2000

Rattling noise when driving

On the above-mentioned vehicles with automatic or manual air conditioning systems, rattling compressor noises can sometimes be heard when driving (with the air conditioning system switched on). These noises can be caused or intensified by there being too little refrigerant in the system. The noise problem can be solved or lessened by refilling the system with the amount of refrigerant prescribed by the vehicle manufacturer.

Bulletin