



BMW X5 (E53)

Noises from the central interior air vent

In the case of the above-mentioned vehicles, noises may come from the central interior air vent when driving. If the vent is closed, the noise can no longer be heard. The cause of the noise is linked to the installation location and the design of the condensed-water drain. The end of the drain is open in the engine bay, above the crankshaft. As a result of this, driving and engine noises can be transmitted into the interior via the condensed-water drain and the air vent. To resolve the problem, the manufacturer offers a special valve for fastening to the end of the condensed-water drain.

Bulletin