



Citroen

C2, C3, C4, Xsara, Picasso, Berlingo 2

Model: 2006 | 2007

Various petrol engines

Coolant temperature sensor defective / Engine malfunction

In the case of the above-mentioned vehicles, a defective coolant temperature sensor can lead to various engine malfunctions (e.g. irregular engine running).

In relation to the problem, the vehicle manufacturer has a service campaign in the course of which vehicle owners have been contacted. However, it should not necessarily be assumed that all vehicles have been dealt with under this campaign and that vehicle owners have had the check/replacement of the temperature sender unit carried out.

Please take this into account if there are complaints with regard to engine running.

Bulletin