



Citroen

C5

Model year: 2000–2004

Engine: 2.0 D HDi

Permanent operation of the radiator fan/Battery discharged

In the case of the above-mentioned vehicles, a defective radiator-fan relay may be the cause of the radiator fan running permanently or/and of the battery being discharged. Please take this into account, particularly where complaints in connection with a discharged battery are concerned. The radiator-fan relay is in the area of the coolant radiator.

Bulletin