



## **Citroen C5**

**Model year 2004 ⇒**

**All vehicles with HDI engines and air-conditioning system**

**Coolant control lamp illuminates**

If there are complaints about the above-mentioned fault, the cause could be defective radiator fan relays. Furthermore, it may be that the coolant control lamp illuminates, but the temperature gauge in the cockpit indicates a normal value. In addition, there may also be complaints that when switching on the air-conditioning system the coolant control lamp illuminates. In this case, the three radiator fan relays must be checked and, if necessary, replaced. These are located at the lock carrier below the plastic cover (see illustration.)



**Bulletin**