



CITROËN

C8

Year of manufacture: 2002 - 2005

Condensation water outflow / Airbag monitoring light

Problem:

Accumulation of water in the passenger foot room area. In some cases water gets into the airbag control device, which can cause the monitoring light to light up. In an extreme case, the airbag is activated.

Possible cause:

Defective runoff of condensation water from the air conditioner.

Remedy:

Check and clean out the condensation water; check the airbag device for entry of water.
Obtain further information on remedies from the auto manufacturer.

Bulletin