Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall

01. Oktober 2005

1-1

Fiat Doblo All models

Noises and poor performance of the ventilation system.

If there are complaints with these vehicles that the ventilation system is noisy and performs poorly, one possible cause is soiling of the air intake aperture and the air guide. To eliminate the fault, the air guide has to be cleaned and an additional protective grill installed. To do this proceed as follows:

- Remove the blower motor (footwell on passenger side).
- Remove the windscreen wiper and the trim below the windscreen as well.
- On both sides, remove all dirt from the air intake aperture and the air guide.
- Fit the additional protective grille (a necessary spare part) over the air intake opening (is simply kept in place by existing clips).
- Refit the components in the reverse order to removal.
- Check for proper operation of the ventilation system.

Bulletin

