



FIAT

Grande Punto (199)

Model year: 12.2006 to 10.2007

Functional failure of the heater blower

With the above-mentioned vehicles, the heater blower can fail due to a cable possibly being routed incorrectly.

In addition, there is a short-circuit and fire hazard. Vehicles from the production period December 2006 to October 2008 are affected.

The owners of the vehicles concerned have been notified by the manufacturers and asked to have their vehicle checked over. The cable may have to be relaid. It must be assumed, however, that not all vehicle owners have followed this request or that not all vehicles have been checked / improved. In the event of such damage, contact an authorized Fiat dealer.

Bulletin