Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall Q1 / 2013 1-1


Fiat Scudo 1.6D Multijet 90 Year of manufacture: from 2007 until VIN ⇒ 84160387

Poor air conditioning system performance

If the vehicles mentioned above experience poor air conditioning performance or a loss of coolant, the possibility of a coolant leakage between the condenser and compressor must be considered.

Check the coolant line for the correct model type and replace if necessary. (see figures)






- Old model types -

This is the modified model type from the vehicle manufacturer: [Spare parts]

1 unit: Coolant line: (Spare parts): 1401422802 units: O-ring: (Spare parts): 9645950980



- New model type -

Bulletin