



Fiat

Ulysse

Engine: 2.0 + 2.2 l diesel

Model year: June 2002 - November 2004

Condensation drain / Airbag

With the above-mentioned vehicles, a faulty air-conditioning condensation drain can lead to problems with the airbag system.

If condensation cannot drain off properly, humidity may penetrate the vehicle interior or the airbag control unit. This can cause a fault in the airbag system. This is indicated by the airbag control lamp lighting up. In extreme cases, the airbag(s) can trigger.

The vehicle manufacturer has already recognized the problem and informed the vehicle owners affected. It must be assumed, however, that for a variety of reasons not all vehicles have been checked and/or repaired.

Please bear this information in mind when dealing with complaints about the airbag system or water penetrating the vehicle interior.

Check the lower engine cover too in the above-mentioned vehicles. This can become loose during driving or after servicing work.

Bulletin