



Ford Mondeo II Model year 1996-2000 With air conditioning system

Loss of refrigerant from the condenser

If refrigerant loss from the air conditioning system is detected with the above-mentioned vehicles, the condenser should be examined particularly carefully. These can be so heavily corroded that they become leaky. Please do not forget to examine the rear and underside of the condenser.


Replacement condensers can be found in the Hella air conditioning range:

Mondeo II Model year: 9/96-3/99 Part no.: 8FC 351 035-581

Mondeo II Model year: 3/99-11/00 Part no.: 8FC 351 037-711



8FC 351 035-581



8FC 351 037-711

Bulletin