



Ford

Focus

Model year: until June 2000

With air-conditioning system

Strong development of odour, fogged windows

Strong, musty odour development and/or fogged windows can occur in the case of the above-mentioned vehicles. This is often caused by moisture residues in the evaporator box or on the surface of the evaporator. When switching on the interior blower, the moisture condenses on the windows. In addition, it may be that micro-organisms have settled in the area of the evaporator. These micro-organisms contribute to a strong musty odour. In the event of complaints in connection with bad-smelling odours, the evaporator should be disinfected. In order to prevent the windows fogging, an electric add-on module can be installed. 45 minutes after the ignition is switched off, the module switches the blower fan on for a few minutes. This dries the surface of the evaporator and the evaporator housing. The add-on module can be obtained via an authorized dealer.

Bulletin