Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 01. Oktober 2005 1-2

Ford Galaxy from model year 06/2000 Seat Alhambra from model year 04/2000 VW Sharan from model year 04/2000

Change to charge quantities

After the "facelift" of the above models, the charge level for the air conditioning system was changed for design reasons. In the case of some information in the marketplace, the old charge quantities were not revised after the "facelift" and have continued to be used. The correct charge quantities are stated in the following table:

	Refrigerant type	Refrigerant quantity (g)	Oil type	Oil quantity (ml)
Ford Galaxy with Sanden compressor	R134a	700-750	PAG Iso 46	135
Ford Galaxy with Sanden compressor and rear air conditioning system	R134a	1050-1100	PAG Iso 46	240
Ford Galaxy with Visteon FS10 compressor	R134a	700-750	PAG Iso 46	200
Ford Galaxy with Visteon FS10 compressor and rear air conditioning system	R134a	1050-1100	PAG Iso 46	240





Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 01. Oktober 2005 2-2

	Refrigerant type	Refrigerant quantity (g)	Oil type	Oil quantity (ml)
Seat Alhambra	R134a	700-750	PAG Iso 46	135
Seat Alhambra with rear air conditioning system	R134a	1050-1100	PAG Iso 46	240
VW Sharan	R134a	700-750	PAG Iso 46	135
VW Sharan with rear air conditioning system	R134a	1050-1100	PAG Iso 46	240

